

Appendix B Photographs of the Project area



Photo 1 West aspect of constructed CRS-1 crossing at Km 0 of the North Pole River access road, marine Tariuraq Inlet on the left side of photo and the freshwater lake on the right side; no culverts installed.



Photo 2 South aspect from the constructed CRS-1 crossing; marine Tariuraq Inlet in background.

Appendix B: Photographs of the Project area



Photo 3 North aspect from constructed CRS-1 crossing; the freshwater lake in background.



Photo 4 Km 0.5 of constructed access road, note bedrock ridges and vegetated slopes; north aspect.



Photo 5 Km 0.5 of constructed access road, note bedrock ridges on east and west; south aspect with Tariuraq Inlet in far background of photo.



Photo 6 CRS-2 crossing at Km 1.8 of the constructed access road, north aspect with installed culvert and downstream flow pattern.

Appendix B: Photographs of the Project area



Photo 7 CRS-2 crossing west aspect with installed culvert and upstream pond flow pattern; upstream water body is confirmed fish-bearing pond.



Photo 8 End of constructed access road with existing ATV trail near Km 2.9 of the proposed route; north aspect.