NWB Annual	Report	Year being reported: Select ▼
License No:	8WLC-AWL1516	Issued Date: June 20, 2015 Expiry Date: Jue 20, 2016
	Project Name:	Arctic Watch Lodge
	Licensee:	Canadian Arctic Holidays Ltd
	Mailing Address:	363 Pritchard Rd Alcove, QC
		J0X1A0
		filing Annual Report (if different from Name of Licensee please veen the two entities, if applicable):
General Bac	kground Information	n on the Project (*optional):
Licence Requirements		see must provide the following information in accodance
	ter; sewage and gre	and waste disposal activities, including, but not limited to: methods of eywater management; drill waste management; solid and hazardous
	Water Source(s): Water Quantity:	Cunningham River 5
Ī	Waste Management Solid Waste D Sewage Drill Waste Greywater Hazardous Other: Additional Details:	Disposal
		cnife for disposal: household garbage 1350lbs, 15 gal waste oil, 210lbs glass, 300 lbs scrap steel, 350 lbs ash d to Resolute 40 empty drums, 2 propane cylinders

A list of unauthorized discharges and a summary of follow-up actions taken.

	Spill No.: (as reported to the Spill Hot-line) Date of Spill:			
	Date of Notification to an Inspector: Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)			
Revisions to	the Spill Contingency Plan			
	SCP submitted and approved - no revision required or proposed			
	Additional Details:			
Revisions to	the Abandonment and Restoration Plan			
	AR plan submitted and approved - no revision required or proposed			
	Additional Details:			
Progressive	Reclamation Work Undertaken Additional Details (i.e., work completed and future works proposed)			
Deculte of th	Monitoring Drogram including.			
Results of th	e Monitoring Program including:			
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;			
	Details described below			
	Additional Details:			
	74° 04.167' north, 93° 48.798' west			
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited; Details described below			
	Additional Details:			
	Black water sewage sump: 74° 04.213'north, 93° 48.975' Incinerator (wood, paper) 74° 04.392north, 93° 48.644' Grey water sump/leaching bed 100 m from Black water sump			

Results of any additional sampling and/or analysis that was requested by an Inspector

	Colort			
	Select			
	Additional Details: (date of request, analysis of results, data attached, etc)			
Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.				
	Select			
	Additional Details: (Attached or provided below)			
Any respons	es or follow-up actions on inspection/compliance reports			
•	Select			
	Additional Details: (Dates of Report, Follow-up by the Licensee)			
	Traditional Delation (Dates of Treport, Femore ap 2) the Electroscop			
Any addition <u>al comments or information for the Board to consider</u>				
'				
Date Submit	ted: March 15, 2016			
Submitted/P				
Contact Info	rmation: Tel: 819 459 1794			
	Fax: email: mail@arcticwatch.ca			
	eman. mane archievatori.ca			