

NWB Annual Report

Year being reported:

Select



2016

License No: 8WLC-CGM1617

Issued Date:

April 15, 2016

Expiry Date:

April 14, 2017

Project Name:

Marine Habitat Use of Thick Billed Murres Nesting at Cape Graham Moore, Nunavut

Licensee:

Environment and Climate Change Canada; National Wildlife Research Centre

Mailing Address:

National Wildlife Research Centre
1125 Colonel By Drive
Ottawa, ON, K1S 5B6

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B



Item 1



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Pond Inlet municipal water supply & melted snow/sea ice

Water Quantity:

1 cu.m/day

Quantity Allowable Domestic (cu.m)

0.2 cu. m/day

Actual Quantity Used Domestic (cu.m)

0

Quantity Allowable Drilling (cu.m)

0

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☒ Solid Waste Disposal☒ Sewage☐ Drill Waste☒ Greywater☐ Hazardous☐ Other:

Additional Details:

Greywater and sewage was disposed of in a sump more than 100m from any water source and buried before leaving camp. Burnable waste items were incinerated. Non-burnables and residues were transported to Pond Inlet for disposal.

A list of unauthorized discharges and a summary of follow-up actions taken.Spill No.: (as reported to the Spill Hot-line)Date of Spill: Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

Revisions to the Abandonment and Restoration Plan

N/A - not applicable



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Results of the Monitoring Program including:**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details described below



Additional Details:

Temporary Camp location: 72.936914°N, -76.119418°W

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below



Additional Details:

Greywater and sewage was disposed of in a sump more than 100m from any water source and buried before leaving camp (temporary camp location:

72.936914°N, -76.119418°W

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

Date Submitted:

March 16, 2016

Submitted/Prepared by:

Grant Gilchrist / Jake Russell-Mercier

Contact Information:

Tel: 613 998-7364

Fax:

email: grant.gilchrist@canada.ca