

NWB Annual Report

Year being reported:

Select ▼

2017

License No: 8WLC-DIS1718

Issued Date: July 4, 2017

Expiry Date: July 3, 2018

Project Name: Periglacial and Paleoglacial Investigation of the Haughton Impact

Licensee: Etienne Godin

Mailing Address: Department of Earth Sciences  
University of Western Ontario  
1151, Richmond Street,  
London, ON, N6A 5B7

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Etienne Godin

General Background Information on the Project (\*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Select ▼ Select ▼

**A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.**

Water Source(s):	Haughton River	
Water Quantity:	1	Quantity Allowable Domestic (cu.m)
	0.1	Actual Quantity Used Domestic (cu.m)
	0	Quantity Allowable Drilling (cu.m)
	0	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☒ Sewage
- ☐ Drill Waste
- ☒ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

Abovementioned water quantities are in cubic meter per day.  
Greywater was disposed in an isolated pit (15 L daily) as well as sewage

**A list of unauthorized discharges and a summary of follow-up actions taken.**

Spill No.: NONE (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

### Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

### Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

2 pit were recovered with original material and to their prior state

### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details described below



Additional Details:

Haughton River 75° 22' 23" N - 89° 31' 20" W

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details described below



Additional Details:

Grey Water 75° 22' 25" N - 89° 31' 54" W  
Sewer 75° 22' 26" N - 89° 31' 58" W

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

All other waste was flown out

**Date Submitted:**

13/11/2017

**Submitted/Prepared by:**

Etienne Godin

**Contact Information:**

**Tel:** 5146472118

**Fax:**

**email:** egodin5@uwo.ca

### GPS Coordinates for water sources utilized

[illegible]

### GPS Locations of areas of waste disposal

[illegible]