



Water Licence Inspection Report

☒ Original
☐ Follow-Up Report

Authorization	Representative
Canadian Museum of Nature	Dr. Lynn Gillespie
Authorization No. / Expiry	Representative's Title
8WLC-FCA2021	
Activities Inspected	
<input checked="" type="checkbox"/> Camp, Commercial <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Winter Hauling <input type="checkbox"/> Camp, Private <input type="checkbox"/> Other	

Section 1 Comments
<p>On June 25, 2024 I, Sean Noble-Nowdluk, Inspector with Crown-Indigenous Relations and Northern Affairs Canada (CIRNAC) completed an Inspection of the sites for the purpose of verifying compliance with the terms and conditions of which this water license was issued upon.</p> <p>This license had expired on April 30, 2021 and after an aerial survey of the sites, it appears to be left in pristine condition and satisfactory to the Inspector. No signs of any structures or equipment were observed during the inspection. I recommend this Water License be closed with the Nunavut Water Board.</p>
Section 2 Non-Compliance with Acts or License
No compliance issues were observed during this inspection.
Section 3 Action Required
No action is required, recommending closure of this Water License.

Licensee or Representative	Inspector's Name
	Sean Noble-Nowdluk
Signature	Signature
	<i>Sean Noble-Nowdluk</i>
Date	Date
	November 20, 2024

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---



PHOTO LOG

Date:	Authorization Number:	Camera/Model:	Inspector
Tuesday, June 25, 2024	8WLC-FCA2021	SamsungS23	Sean Noble-Nowdluk
Photo No. 1		Lat/Long (DD.MM.SS.SS, NAD83)	
Photo			



Description:

Aerial view of general area of camp. No equipment was observed at this area.



Photo No. 2

Lat/Long (DD.MM.SS.SS, NAD83)

Photo



Description:

Aerial view of general area of camp. No equipment was observed at this area.



Photo No. 3

Lat/Long (DD.MM.SS.SS, NAD83)

Photo



Description:

Aerial view of general area of camp. No equipment was observed at this area.