# WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

| Licensee | Licensee Representative |
|---|---|
| Lynda Gullason | |
| **Licence No. / Expiry** | **Representative's Title** |
| 8WLC-MPP2223 | |
| **Land / Other Authorizations** | **Land / Other Authorizations** |
| N2022N0004 | |
| **Date of Inspection** | **Inspector** |
| July 23, 2026 | Joseph Monteith |

**Activities Inspected**

☐ Camp ☐ Drilling ☐ Mining ☐ Construction ☐ Reclamation ☐ Fuel Storage
☐ Roads/Hauling ☐ Other: ☐ Other:

**Conditions:** **A- Acceptable** **U-Unacceptable** **C-Concern** **NI-Not Inspected** **NA- Not applicable**

| PART: | Condition | Observation No.* |
|---|---|---|
| A: SCOPE, DEFINITIONS AND ENFORCEMENT | | |
| B: GENERAL CONDITIONS | | |
| C: CONDITIONS APPLYING TO SECURITY | | |
| D: CONDITIONS APPLYING TO WATER USE | A | 1 |
| E: CONDITIONS APPLYING TO WASTE DISPOSAL AND MANAGEMENT | A | 2,3,4 |
| F: CONDITIONS APPLYING TO MODIFICATIONS | | |
| G: CONDITIONS APPLYING TO CONSTRUCTION | | |
| H: CONDITIONS APPLYING TO EMERGENCY RESPONSE AND CONTINGENCY PLANNING | | |
| I: CONDITIONS APPLYING TO ABANDONMENT, RECLAMATION AND CLOSURE PLANNING | A | 5 |
| J: CONDITIONS APPLYING TO MONITORING | | |
| SCHEDULES | | |

**The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below.*

| Samples taken by Inspector: | Location(s): N74° 31' 42.0" W82° 26' 20.5" |
|---|---|
| ☐ Yes ☒ No | |

**Background**

## Inspector Statement

On June 30, 2026, Water Resource Officer(WRO) Joseph Monteith water license inspection was conducted on 8WLC-MPP2223 at Dundas Harbour, Devon Island, Nunavut.

## Water Use

1. No signs of water use, or disturbances.

## Waste

2. No signs of sump pit
3. No signs of solid wastes
4. No signs of spills

## Reclamation

**5.** No signs of structures, equipment or spills

**SECTION 1** ☒ **Comments** ☐ **Non-Compliance with Act or Licence** ☐ **Action Required**

Site appears to have been brought to near pristine condition. The Licensee expressed interest in returning to the site and extending her Water License.


**SECTION 2** ☐ **Comments** ☒ **Non-Compliance with Act or Licence** ☐ **Action Required**

| | |
|---|---|
| **Licensee or Representative** | **Inspector's Name** |
| Lynda Gullason | Joseph Monteith |
| **Signature** | **Signature** |
| | |
| **Date** | **Date** |
| | October 19, 2026 |

CC: Licensing Department, NWB
Jeremy Fraser, Manager of Field Operation

**PHOTO LOG**

| **Date** | **Camera** | **Inspector** |
|---|---|---|
| June 30, 2026 | Galaxy S12 | Joseph Monteith |
| **Photo Log #1** | | **Location** |
| Photo 1 | | Dundas harbour, Devon Island, Qikiqtani Region |




**Description: Morin Point, Dundas Harbour. Camp was situated on the North side of the Lake on the point.**

| Photo Log | Location |
|---|---|
| Photo 2 | Dundas harbour, Devon Island, Qikiqtani Region |



**Description: Morin Point, Dundas Harbour,**

| Photo Log | Location |
|---|---|
| Photo 3 | Dundas harbour, Devon Island, Qikiqtani Region |



**Description: Camp was situated on the North West side of the lake on the "terrace".**

| Photo Log | Location |
|---|---|
| Photo 5 | Dundas harbour, Devon Island, Qikiqtani Region |



**Description: Morin Point, Dundas Harbour. Camp on North West side of the lake.**

| Photo Log | Location |
|---|---|
| Photo 5 | Dundas harbour, Devon Island, Qikiqtani Region |



**Description: Morin Point, Dundas Harbour. Camp appears to have been reclaimed.**