NWB Annual Re	port	Year	r being reported:	2010	•	
License No: 3B0	C-NET0913		ed Date: August 7			
Pro	oject Name:	CWS Nikko Island	d Goose Research	Camp		
Lic	ensee: Canadi	an Wildlife Servi	ce			
Ма	iling Address:	Environment C Suite 150-123 I Winnipeg, MB.	Main Street			
	me of Company fil	•	•	Name of Lic	ensee pleas	e clarify
General Backgro	ound Information o	on the Project (*	optional):			
Licence Require with	Part B Tter	ee must provide	the following info	ormation	in accodaı	nce
A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.						
Wa	ater Source(s): ater Quantity:	Nettilling Lake 5 cu. m/day 0.07 cu. m/day n/a n/a	Quantity Allowable Actual Quantity Us Quantity Allowable Total Quantity Use	ed Domes Drilling (c	stic (cu.m) cu.m)	
Add	aste Management an Solid Waste Disp Sewage Drill Waste Greywater Hazardous Other: ditional Details: cinerator has been	oosal	for Household Wa	ste.		

A list of unauthorized discharges and a summary of follow-up actions taken.

	Spill No.: (as reported to the Spill Hot-line)
	Date of Spill: Date of Notification to an Inspector:
	Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)
Revisions to	the Spill Contingency Plan
	SCP addendum attached for Board consideration
	Additional Details:
Revisions to	the Abandonment and Restoration Plan
	AR addendum attached for Board consideration
	Additional Details:
Progressive	Reclamation Work Undertaken
	Additional Details (i.e., work completed and future works proposed)
	Progressive reclamation as requested by the inspector has been ongoing during the life of the permit. An incinerator has been installed on-site for disposal of combustible household waste. Non-combustable material has been removed on an annual basis for disposal and recycling
Results of th	e Monitoring Program including:
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;
	Details described below
	Additional Details:
	Details attached in Spill Contingency Plan
	The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;
	Not Applicable (N/A) ▼
	Additional Details:

	Results of any additional sampling and/or analysis that was requested by an Inspector				
	Select				
	Additional Details: (date of request, analysis of results, data attached, etc)				
Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.					
	No additional sampling requested by an Inspector or the Board				
	Additional Details: (Attached or provided below)				
Any respons	ses or follow-up actions on inspection/compliance reports				
	Inspection Report received by the Licensee (Date):				
	Additional Details: (Dates of Report, Follow-up by the Licensee)				
	July ,2009				
Any addition	al comments or information for the Board to consider				
	Secondary containment and spill kits will be in place for the 2015 field season.				
Date Submit Submitted/P Contact Info	repared by: Marc Schuster				