

NWB Annual Report

Year being reported: Select ▼

License No: 8WLC-NWT1617 **Issued Date:** July 13, 2016
Expiry Date: 12 July, 2017

Project Name: Northern Watch Technology Demonstration Project

Licensee: Andrew MacInnis and Tamara Van Dyck

Mailing Address: 9 Grove Street
Dartmouth, NS
B2Y 3Z7
ATTN: Andrew MacInnis

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Tamara Van Dyck - Defence Construction Canada
DGME - NDHQ 101 Colonel By Drive, Ottawa, ON K1A 0K2

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Select ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

| | | | |
|------------------|-------------------|--------------------------------------|--|
| Water Source(s): | melt water system | | |
| Water Quantity: | 0 | Quantity Allowable Domestic (cu.m) | |
| | | Actual Quantity Used Domestic (cu.m) | |
| | | Quantity Allowable Drilling (cu.m) | |
| | | Total Quantity Used Drilling (cu.m) | |

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

The DRDC team was not on site in the 2016 field season, no waste was managed or disposed of.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

N/A

Revisions to the Spill Contingency Plan

Select 

Additional Details:

N/A

Revisions to the Abandonment and Restoration Plan

Select 

Additional Details:

N/A

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

N/A

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A) 

Additional Details:

The DRDC team was only on site for half a day in the 2013 field season, no waste was managed or disposed of.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A) 

Additional Details:

The DRDC team was only on site for half a day in the 2013 field season, no waste was managed or disposed of.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (date of request, analysis of results, data attached, etc)

N/A

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board ▼

Additional Details: (Attached or provided below)

N/A

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC ▼

Additional Details: (Dates of Report, Follow-up by the Licensee)

N/A

Any additional comments or information for the Board to consider

Date Submitted:

November 2, 2016

Submitted/Prepared by:

Tamara Van Dyck, Defence Construction Canada

Contact Information:

Tel: 613-995-9741

Fax:

email: Tamara.VanDyck@dcc-cdc.gc.ca