



WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
Defence R&D Canada(DRDC)-Atlantic Research Centre	Erin MacNeil
Licence No. / Expiry	Representative's Title
8WLC-NWT2223	Head/Research Engineering & Development
Land / Other Authorizations	Land / Other Authorizations
Reserve	
Date of Inspection	Inspector
July 10, 2023	Joseph Monteith
Activities Inspected	
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Mining
	<input type="checkbox"/> Construction
	<input checked="" type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage
	<input type="checkbox"/> Other:

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
PART:	Condition	Observation No.*			
A: SCOPE, DEFINITIONS AND ENFORCEMENT	A				
B: GENERAL CONDITIONS	A				
C: CONDITIONS APPLYING TO SECURITY	NI				
D: CONDITIONS APPLYING TO WATER USE	A	1			
E: CONDITIONS APPLYING TO WASTE DISPOSAL AND MANAGEMENT	A	2, 3, 4			
F: CONDITIONS APPLYING TO MODIFICATIONS	A				
G: CONDITIONS APPLYING TO CONSTRUCTION	A				
H: CONDITIONS APPLYING TO EMERGENCY RESPONSE AND CONTINGENCY PLANNING	A	6			
I: CONDITIONS APPLYING TO ABANDONMENT, RECLAMATION AND CLOSURE PLANNING	A	5			
J: CONDITIONS APPLYING TO MONITORING	NI				
SCHEDULES	A				
*The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below.					
Samples taken by Inspector:	Location(s):				
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	• N74° 39' 40.0" W91° 16' 40.0" campsite				

Background			
<p>Inspector Statement</p> <p>On July 10, 202s, a Water License inspection by Aerial Survey was conducted by Water Resource Officer(WRO) Joseph Monteith at the sites where 8WLC-NWT2223 is located on Devon Island, NU. The site was in a state of seasonal closure.</p> <p>Water Use</p> <p>1. No signs of water use, or disturbances (photos 2-5).</p> <p>Waste</p> <p>2. No signs of grey water sump pit</p> <p>3. No signs of incineration</p> <p>Spills</p> <p>4. No signs of spills.</p>			
SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
Site was in a state of seasonal closure. No signs of damages, spills, or water use, and waste deposits. No signs of activity.			
SECTION 2	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required

Licensee or Representative	Inspector's Name
	Joseph Monteith
Signature	Signature
Date	Date
	November 22, 2023

CC: Licensing Department, NWB
Jeremy Fraser, Manager of Field Operation

PHOTO LOG


Date	Camera	Inspector
July 10, 2023	Samsung Galaxy S9	Joseph Monteith
Photo Log #1	Location	
Photo 1	Devon Island, Qikiqtani Region, Nunavut	
<div></div>		
Description: Base camp routes, tracks and points. DRDC site and aerial survey tracks of Water License 8WLC-NWT2223		



Photo Log #

Photo 2

Location

N74° 39' 40.0" W91° 16' 40.0"



Description: Site of Gascoyne Inlet campsite. Site was in a state of seasonal closure.

Photo Log #

Photo 3

Location

N74° 39' 40.0" W91° 16' 40.0"



Description: No sign of deposits of grey water waste. No signs of incineration.



Photo Log #

Photo 4

Location

N74° 39' 40.0" W91° 16' 40.0"



Description: Airstrip

Photo Log #

Photo 5

Location

N74° 39' 40.0" W91° 16' 40.0"



Description: Site of water withdrawal. No signs of water withdrawal equipment, no signs of disturbance to water course.