

WATER LICENCE INSPECTION FORM

☒ Original

☐ Follow-Up Report

Licensee	Licensee Representative
White Wolves- Ghosts of the Arctic	Alain Lusignan
Licence No. / Expiry	Representative's Title
8WLC-WWG1516	Film Maker
Land / Other Authorizations	Land / Other Auhorizations
N2015N0021	
Date of Inspection	Inspector
July 5, 2022	Joseph Monteith
Activities Inspected	
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling
<input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Other:
<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
	<input checked="" type="checkbox"/> Reclamation
	<input type="checkbox"/> Fuel Storage

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
PART:		Condition	Observation No.*		
A: SCOPE, DEFINITIONS AND ENFORCEMENT		A			
B: GENERAL CONDITIONS		A			
C: CONDITIONS APPLYING TO SECURITY		NI			
D: CONDITIONS APPLYING TO WATER USE		A	1		
E: CONDITIONS APPLYING TO WASTE DISPOSAL AND MANAGEMENT		A	2-4		
F: CONDITIONS APPLYING TO MODIFICATIONS		A			
G: CONDITIONS APPLYING TO CONSTRUCTION		A			
H: CONDITIONS APPLYING TO EMERGENCY RESPONSE AND CONTINGENCY PLANNING		A			
I: CONDITIONS APPLYING TO ABANDONMENT, RECLAMATION AND CLOSURE PLANNING		A	5		
J: CONDITIONS APPLYING TO MONITORING		NI			
SCHEDULES		A			
*The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below.					
Samples taken by Inspector:		Location(s): <ul style="list-style-type: none"><li>R3-N79° 53' 06.7" W85° 49' 16.1"</li><li>CA-N79° 51' 22.3" W85° 48' 48.2"</li><li>R2-N79° 52' 30.6" W85° 20' 39.1"</li><li>LK-N79° 57' 42.2" W84° 53' 18.6"</li><li>HW-N80° 02' 23.6" W84° 19' 21.0"</li></ul>			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No					

Background	<p>Alain Lusignan applied for a water license to film Arctic Wolves for a film called “White Wolves – Ghosts of the Arctic. On June 1, 2015 8WLC-WWG1516 was issued to Alain Lusignan for the use of water and deposit of waste without a license.</p> <p>Alain was authorized for water use of 0.1 cubic metre per day, deposit of waste and grey water of 0.1 cubic metre per day, all other waste was to be transported off site.</p> <p>Alain established 5 camps sites at Geographical Coordinates (Camp name-GPS):</p> <ul style="list-style-type: none"><li>R3-N79° 53' 06.7" W85° 49' 16.1"</li><li>CA-N79° 51' 22.3" W85° 48' 48.2"</li><li>R2-N79° 52' 30.6" W85° 20' 39.1"</li><li>LK-N79° 57' 42.2" W84° 53' 18.6"</li><li>HW-N80° 02' 23.6" W84° 19' 21.0"</li></ul> <p><b>Inspector Statement</b></p> <p>On July 5, 2022, a Water License inspection by Aerial Survey was conducted by Water Resource Officer(WRO) Joseph Monteith at the sites where 8WLC-WWG1516 were located on Foshiem Peninsula, Ellesemere Island, NU.</p> <p>Water Use</p> <p>1. No signs of water use, or disturbances.</p> <p>Waste</p> <p>2. No signs of sump pit</p>
------------	---

3. No signs of solid wastes
4. No signs of spills

Reclamation

5. No signs of structures, equipment or spills.

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
-----------	--	---	--

Sites appears to have been reclaimed to near pristine conditions. I recommend Closure of the water license 8WLC-WWG1516

SECTION 2	<input type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
-----------	-----------------------------------	---	--

Licensee or Representative	Inspector's Name
Alain Lusignan	Joseph Monteith
Signature	Signature
Date	Date
	November 22, 2022

CC: Licensing Department, NWB  
Jeremy Fraser, Manager of Field Operation

PHOTO LOG


Date	Camera	Inspector
July 5, 2022	Samsung Galaxy S9	Joseph Monteith
Photo Log #1	Location	
Photo 1	Fosheim Peninsula, Ellesmere Island, Qikiqtani Region, Nunavut	
		
Description: Basemap routes, tracks and points. From Left to Right, R3, CA, R2, LK, and HW campsites.		





Photo Log #

Location

Photo 2

N66° 49' 10.1" W63° 52' 59.3



Description: Site of R3 campsite. No signs of structures, equipment or spills in the general vicinity of the campsite.

Photo Log #

Location

Photo 3

N66° 49' 10.1" W63° 52' 59.3



Description: Site of CA campsite. No signs of structures, equipment or spills in the general vicinity of the camp site.





Photo Log #

Location

Photo 4

N66° 49' 10.1" W63° 52' 59.3



Description: Site of R2 Campsite. No signs of structures, equipment or spills in the general vicinity of the camp site.

Photo Log #

Location

Photo 5

N66° 49' 10.1" W63° 52' 59.3



Description: Site of LK Campsite. No signs of structures, equipment or spills in the general vicinity of the camp site.





Photo Log #	Location
Photo 6	N66° 49' 10.1" W63° 52' 59.3
	
Description: Site of HM Campsite. No signs of structures, equipment or spills in the general vicinity of the camp site.	