

WATER LICENCE INSPECTION FORM

☐ Original
 ☐ Follow-Up Report

Licensee	Licensee Representative
Combustion Performance	Gabriel Chocquette
Licence No. / Expiry	Representative's Title
8WLW-WAG2122	Co-Owner
Land / Other Authorizations	Land / Other Authorizations
Date of Inspection	Inspector
August 24, 2021	Joseph Monteith
Activities Inspected	
<input type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage	
<input type="checkbox"/> Roads/Hauling <input type="checkbox"/> Other: Water Withdraw, <input type="checkbox"/> Other: discharge raw water	

Conditions:	A- Acceptable	U-Unacceptable	C-Concern	NI-Not Inspected	NA- Not applicable
PART:	Condition		Observation No.*		
A: SCOPE, DEFINITIONS AND ENFORCEMENT					
B: GENERAL CONDITIONS					
C: CONDITIONS APPLYING TO SECURITY					
D: CONDITIONS APPLYING TO WATER USE			1		
E: CONDITIONS APPLYING TO WASTE DISPOSAL AND MANAGEMENT			3		
F: CONDITIONS APPLYING TO MODIFICATIONS					
G: CONDITIONS APPLYING TO CONSTRUCTION					
H: CONDITIONS APPLYING TO EMERGENCY RESPONSE AND CONTINGENCY PLANNING					
I: CONDITIONS APPLYING TO ABANDONMENT, RECLAMATION AND CLOSURE PLANNING					
J: CONDITIONS APPLYING TO MONITORING			2		
SCHEDULES					
*The item number corresponds with specific conditions within the licence and the observation number corresponds with specific comments provided below.					
Samples taken by Inspector:		Location(s): Dead Dog Lake Water Intake : N63°44'49.9'', W68°29'21.0''			
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Carney Creek Water intake: N63°44'49.7'',W68°31'57.4''			

Background
<p>On August 23, 2021 Water License 8WLW-WAG2122 was issued to Combustion Performance Inc. For the Approval for Use of Waters Without a License. Authorizing the water use not to exceed 15m³ per day. Effective August 23, 2021, expiring August 22, 2022.</p>
<p>Inspector Statement</p> <p>On August 24, 2021 a water license inspection was conducted by Water Resource Officer (WRO) Joseph Monteith to verify compliance with 8WLW-WAG2122.</p>
<p>Inspection</p> <p>Water Use</p> <ol style="list-style-type: none"> Water is withdrawn from Dead Dog Lake (photo 1) and Carney Creek. Water License observed on site at the time of the inspection (photo 2). Water Usage Logs Observed onsite at the time of the inspection. Each log date states 1000 Litres. Dates in log run contrary to Subsection 11(1) of the Nunavut Waters, and Nunavut Surface Rights Tribunal Act (photo 3,4,5). Withdrawn water is stored in a Water Storage Tank (photo 6) Water is withdrawn using a Mobile Water Pump (photo 7) <p>Deposit of Waste</p> <ol style="list-style-type: none"> 3x pails observed on site. Each pail is roughly 8 to 12 Litres is used to wash vehicles. The raw water mixed with soap run off from the cleaned vehicles is the deposit of waste (photo 8). No concerns for deposit of waste, as site of cleaning is over 31 metres from any water body.



SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input checked="" type="checkbox"/> Action Required
<p>It was noted in the log book, dates of water withdraw, that Combustion Performance Inc., was operating with an expired water license. 8WLW-WAG1920 expired in August 18, 2020.</p> <p>Action Required</p> <p>-In future, do not withdraw water unless you have been given approval by the Nunavut Water Board to operate with a valid water license.</p>			
SECTION 2	<input type="checkbox"/> Comments	<input checked="" type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<p>Nunavut Waters, and Nunavut Surface Rights tribunal</p> <p>Subsection 11 (1) <i>Subject to subsection (2), no person shall use, or permit the use of, waters in Nunavut except in accordance with the conditions of a licence.</i></p>			

Licensee or Representative	Inspector's Name
	Joseph Monteith
Signature	Signature
Date	Date
	November 29, 2021

CC: Licensing Department, NWB
Justin Hack, Manager of Field Operations

PHOTO LOG

Date	Camera	Inspector
August 24, 2021	Nikon Coolpix	Joseph Monteith
Photo Log #1	Location	
Photo 1	Dead Dog Lake, Iqaluit, NU	

Description: Site of Water Withdraw for Dead Dog Lake.




Photo Log

Location

Photo 2

Northmart Parking Lot, Iqaluit, NU




Description: Water License onsite at the time of inspection

Photo Log #

Location

Photo 3

Northmart Parking Lot, Iqaluit, NU



Description: August 14, 2021 1000 Litres. 14 count is number of customers




Photo Log #

Photo 4

Location

Northmart Parking Lot, Iqaluit, NU




Description: August 15, 1000 Litres. 27 count, is number of customers

Photo Log #

Photo 5

Location

Northmart Parking Lot, Iqaluit, NU



Description: Water Usage Log for August 24, 2021. 1000 Litres noted.



Photo Log #

Photo 6

Location

Northmart Parking Lot, Iqaluit, NU



Description: Water Storage Tank

Photo Log #

Photo 7

Location

Northmart Parking Lot, Iqaluit, NU



Description: Mobile Water Pump



Photo Log #

Location

Photo 8

Northmart Parking Lot, Iqaluit, NU



Description: Raw water is mixed with soap to wash cars. The run off from the car wash is the deposit of waste.