

DAILY SITE REPORT

Project Name: City of Iqaluit Sewage Lagoon West Dyke Repairs

Report #: 1

Date: August 12, 2006

Report by: Paul Matergio **Project No.:** 06-1426

Distribution: City of Iqaluit (Geoff Baker)

File

Weather: Clear, +16°C

Contractor: BBS Construction

Personnel on Site: 2

Equipment: Cat 235 Excavator, Tri-Axle Dump, Cat 950 Loader

Progress:

- Arrival on site at approximately 0700 hours. A brief meeting was held on site for introductions (construction foreman is Bill from BBS) and progress overview.
- Progress to date has comprised:
 - Removal of existing rip-rap material on southern portion of downstream face
 - Removal of debris from work area
 - > Discussion of areas of berm requiring slope flattening
 - ➤ Backfilling of southern portion of downstream face to an approximately 6:1 slope
 - ➤ Visit to quarry to view backfill materials (engineered fill)

1420 Blair Place, Suite 104, Ottawa, Ontario. K1J 9L8 Tel.: 613 824 8900 Fax.: 613 824 8901